



2000 S TYPE CLIMATE CONTROL REMOVAL INFORMATION


Center Control Console Removal




1. **Remove the center control panel screw covers.**




Detach the center control panel.




Disconnect the heated seat electrical connectors



Disconnect the climate control unit electrical connectors




Disconnect the satellite navigation screen electrical connectors ,If applicable




Remove the center control panel. Disconnect the audio system electrical connector.


NOTE: When the battery is disconnected and reconnected all previous panel settings and fault codes will be lost. It is necessary to record any non-standard settings or fault codes before battery disconnection to prevent customer complaint and carry out correct diagnosis.



Remove the control assembly screws



Remove the control assembly screws



Remove the control assembly